

The DN side isolators mounting plate is used for mounting PTH or resin bushings with ATEX APTH marking. Mounting bolts M10 are used for the assembly of insulators and complete sheet metal in the transformer chamber.

The plate fixing the LV side insulators is installed in the transformer chamber in flameproof transformer stations of the IT3S ... type and the series of flameproof transformer stations type MAR -....

